





UPS HAT



WARNING



BCM	wPi	3V3	RPi	5V	wPi	BCM
2	8	1	2	5V		
3	9	3	4	5V	15	14
4	7	5	6	GND	16	15
		7	8		1	18
17	0	9	10			
27	2	11	12	GND		
22	3	13	14			
		15	16		4	23
10	12	17	18	GND	5	24
9	13	19	20			
11	14	21	22		6	25
		23	24		10	8
0	30	25	26		11	7
5	21	27	28	GND	31	1
6	22	29	30			
13	23	31	32	GND	26	12
19	24	33	34			
26	25	35	36		27	16
		37	38		28	20
		39	40		29	21